






# PQC setup status

### Probe card









Speck on one of the needles successfully removed using a probe needle




#### Probe card







Probe card alignment checked and looks good – all needles touch down at the same time







#### IHEP non-irradiated



40 60 80 100 120 140 160 180 20 Bias Voltage [V] 20 40 60 80 100120140160180200 V [V]



## Backup

