



# USTC\_W3-19\_0e14\_main sensor test

- Recycled main sensor from LTS study
- Mounted on Santa Cruz board
  - Col 3 Row 2 to signal
  - All other pixels + guard ring to GND
- - 30 C
- Analysis done this morning, needs a little refining


USTC\_W3-19\_0e14\_main



Leakage current T = 0 C



USTC\_W3-19\_0e14\_main



USTC\_W3-19\_0e14\_main

